



DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0395; Project Identifier MCAI-2021-01048-T]

RIN 2120-AA64

Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (SNPRM).

SUMMARY: The FAA proposes to revise a notice of proposed rulemaking (NPRM) to supersede Airworthiness Directive (AD) 2018-18-05, which applies to certain ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes; and AD 2020-09-16, which applies to all ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. This action revises the NPRM by including additional new or more restrictive airworthiness limitations. The FAA is proposing this AD to address the unsafe condition on these products. Since this action would impose an additional burden over those in the NPRM, the FAA is reopening the comment period to allow the public the chance to comment on these changes.

DATES: The FAA must receive comments on this SNPRM by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- Hand Delivery: Hand deliver to Mail address above.

For material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-0395.

Examining the AD Docket

You may examine the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-0395; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this SNPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3220; email shahram.daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include “Docket No. FAA-2022-0395; Project Identifier MCAI-2021-01048-T” at the beginning

of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this SNPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this SNPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this SNPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this SNPRM. Submissions containing CBI should be sent to Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3220; email shahram.daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2018-18-05, Amendment 39-19384 (83 FR 44463, August 31, 2018) (AD 2018-18-05), for certain ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. AD 2018-18-05 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance requirements and airworthiness limitations. The FAA issued AD 2018-18-05 to prevent reduced structural integrity of the airplane.

The FAA also issued AD 2020-09-16, Amendment 39-19912 (85 FR 29596, May 18, 2020) (AD 2020-09-16), which applies to all ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. AD 2020-09-16 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2020-09-16 to address reduced structural integrity of the airplane. AD 2020-09-16 specifies that accomplishing the revision required by paragraph (g) of that AD terminates all requirements of AD 2018-18-05.

The FAA issued an NPRM to amend 14 CFR part 39 by adding an AD to supersede AD 2018-18-05 and AD 2020-09-16 that would apply to all ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. The NPRM published in the *Federal Register* on April 6, 2022 (87 FR 19818) (the NPRM). The NPRM was prompted by MCAI originated by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union. EASA issued AD 2021-0211, dated September 17, 2021 (EASA AD 2021-0211), to correct an unsafe condition. The NPRM proposed to retain the requirements of AD 2020-09-16. The NPRM also proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

Actions Since the NPRM Was Issued

Since the FAA issued the NPRM, EASA superseded EASA AD 2021-0211 and issued EASA AD 2022-0062, dated April 8, 2022 (EASA AD 2022-0062) (also referred to after this as the MCAI). The MCAI states that since EASA AD 2021-0211 was issued ATR published Revision 11 of the ATR 42-200/-300/-320 Time Limits Document (TLD), which includes new or more restrictive maintenance tasks and airworthiness limitations.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-0395.

Comments

The FAA received a comment from The Air Line Pilots Association, International (ALPA), who supported the NPRM without change.

Related Service Information Under 1 CFR Part 51

EASA AD 2022-0062 describes new or more restrictive maintenance tasks and airworthiness limitations for airplane structures and components.

This proposed AD would also require EASA AD 2019-0256, dated October 17, 2019, which the Director of the Federal Register approved for incorporation by reference as of June 22, 2020 (85 FR 29596, May 18, 2020).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this NPRM after

determining that the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

Certain changes described above expand the scope of the NPRM. As a result, it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this SNPRM.

Proposed AD Requirements in this SNPRM

This proposed AD would retain the requirements of AD 2020-09-16. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive maintenance tasks and airworthiness limitations, which are specified in EASA AD 2022-0062 described previously, as proposed for incorporation by reference. Any differences with EASA AD 2022-0062 are identified as exceptions in the regulatory text of this AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections) and Critical Design Configuration Control Limitations (CDCCLs). Compliance with these actions and CDCCLs is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance (AMOC) according to paragraph (m)(1) of this proposed AD.

Costs of Compliance

The FAA estimates that this proposed AD affects 26 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2020-09-16 to be \$7,650 (90 work-hours x \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours x \$85 per work-hour).

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by:

- a. Removing Airworthiness Directive (AD) 2018-18-05, Amendment 39-19384 (83 FR 44463, August 31, 2018); and AD 2020-09-16, Amendment 39-19912 (85 FR 29596, May 18, 2020); and

- b. Adding the following new AD:

ATR-GIE Avions de Transport Régional: Docket No. FAA-2022-0395; Project Identifier MCAI-2021-01048-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

This AD replaces AD 2018-18-05, Amendment 39-19384 (83 FR 44463, August 31, 2018); and AD 2020-09-16, Amendment 39-19912 (85 FR 29596, May 18, 2020) (AD 2020-09-16).

(c) Applicability

This AD applies to all ATR-GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to prevent reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of the Existing Maintenance or Inspection Program, with New Terminating Action

This paragraph restates the requirements of paragraph (g) of AD 2020-09-16, with a new terminating action. Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0256, dated October 17, 2019 (EASA AD 2019-0256). Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

(h) Retained Exceptions to EASA AD 2019-0256, with No Changes

This paragraph restates the exceptions specified in paragraph (h) of AD 2020-09-

16, with no changes.

(1) The requirements specified in paragraphs (1) and (3) of EASA AD 2019-0256 do not apply to this AD.

(2) Where paragraph (2) of EASA AD 2019-0256 refers to its effective date, this AD requires using June 22, 2020 (the effective date of AD 2020-09-16).

(3) Paragraph (4) of EASA AD 2019-0256 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the “limitations, tasks and associated thresholds and intervals” specified in paragraph (4) of EASA AD 2019-0256 within 90 days after June 22, 2020 (the effective date of AD 2020-09-16).

(4) The initial compliance time for doing the tasks specified in paragraph (4) of EASA AD 2019-0256 is at the applicable “associated thresholds” specified in paragraph (4) of EASA AD 2019-0256, or within 90 days after June 22, 2020 (the effective date of AD 2020-09-16), whichever occurs later.

(5) The provisions specified in paragraphs (5) and (6) of EASA AD 2019-0256 do not apply to this AD.

(6) The “Remarks” section of EASA AD 2019-0256 does not apply to this AD.

(i) Retained Restrictions on Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs), with New Exception

This paragraph restates the requirements of paragraph (i) of AD 2020-09-16, with a new exception. Except as required by paragraph (j) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2019-0256.

(j) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022-0062, dated April 8, 2022 (EASA AD 2022-0062). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2022-0062

(1) The requirements specified in paragraph (1) and (2) of EASA AD 2022-0062 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022-0062 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022-0062 is at the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2022-0062, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2022-0062 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2022-0062 does not apply to this AD.

(l) New Provisions for Alternative Actions, Intervals, and CDCCLs

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2022-0062.

(m) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR-GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Related Information

(1) For EASA AD 2022-0062, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-0395.

(2) For more information about this AD, contact Shahram Daneshmandi,

Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200
South 216th St., Des Moines, WA 98198; telephone 206-231-3220; email
shahram.daneshmandi@faa.gov.

Issued on September 19, 2022.

Christina Underwood, Acting Director,
Compliance & Airworthiness Division,
Aircraft Certification Service.

[FR Doc. 2022-20616 Filed: 9/22/2022 8:45 am; Publication Date: 9/23/2022]